



Xerus Firmware 3.6.30

**Date:** January 29, 2021

Version: Xerus 3.6.30 / Build 47403 / Release Notes, Version 2

Release Status: Limited Availability (LA) for select Xerus based products

## **Release Overview**

Xerus™ Firmware 3.6.30 is an **Incremental Release** for select Xerus based products. It includes performance and productivity improvements, new features, and fixes for specific model families.

# **Applicability**

This firmware release applies to the following Xerus-based product brands and models.

Product	Applicable Brand: Model
PDU	Raritan: PX3, PXO Legrand: LP Switched, LP Metered
Branch Circuit Monitor	Raritan: BCM2

## General Guidelines for this Release

Some custom-engineered models will not be supported by this release. Please check the **Not Supported in This Release** section below. Or, contact Raritan Support if you are unsure of the model number of your unit; it is typically viewable from the GUI *Device Information* page, and is printed on a label on the side of the PDU.

Note: Per California Senate Bill 327, Xerus Firmware has updated its default password policy.

*Note*: Do NOT upgrade ANY other Raritan PX model(s) to Xerus 3.6.30 (other than what's listed in the table above) because the unit may have been built after this release entered our System Tests and it may result in the unit becoming non-functional.

*Note*: Do NOT downgrade your new Xerus based products to any prior release. Due to significant internal enhancements in Xerus 3.6.30, a downgrade from the Release 3.6.30 Build 47403 to ANY prior release is NOT SUPPORTED. Please contact Raritan Support with any questions.

Note: Only Power IQ® (DCIM software from Sunbird®) v6.0 and higher are supported with Xerus 3.6.30.



# **Release Highlights**

#### **New Products & Accessories**

Issue ID	Description
Various Added support for Zigbee wireless sensors (Legrand brand PDUs only)	

#### **New Features & Enhancements**

Issue ID	Description
76161	Added originating device info to HTTP data push
76141	USB-B port lockdown

#### **Bug Fixes**

Issue ID	Description
76626	Fixed LDAP authentication issues upgrading from 3.6.1 to 3.6.10/3.6.20
76527	Fixed bug that prevented BCM2 to properly function with SmartLock sensors
76548	Fixed bug that prevented some SNMP traps to be sent to multiple locations/receivers

#### **Security Fixes & Updates**

Issue ID	Description
76253	Updated default TLS certificate expiration (2 years)

Please consult the appropriate User Guide for more information on these firmware features at Raritan.com/support.

## Not Supported with Xerus 3.6.30

Except for some recent Engineered to Order (ETO) models, all above applicable models (above) can be upgraded to this release.

#### **Power IQ & New Hardware Support:**

DX2-DH2C2 (SmartLock Door Handle Controller) is compatible with Power IQ release 6.1.1 and later

#### **Unsupported Accessory Configurations:**

• AMS-M2-Z (*Modular AMS Strip*) Hot Plugging – These asset management accessories cannot be hot-plugged and doing so may result in a controller re-boot or the need to re-boot (power down) the entire PDU.



#### **Default System Passwords:**

 Per California Senate Bill 327, Xerus Firmware has updated its default password policy. Passwords must now be manually set on all new units running Xerus 3.6.0 (and later) or devices that are running Xerus 3.6.0 (and later) and have been factory reset.

If you are unsure that your model is supported by this firmware or you have any questions about unsupported configurations, please contact your regional support team at Raritan.com/support.

# **Upgrade Matrix (Path for Upgrades)**

This release is intended for factory shipments and firmware upgrades on the series/models stated in the table above.

Please Note: Due to file system changes in Xerus 3.6.30 and earlier releases, the following upgrade paths need to be followed or the Xerus device may become inoperable and require manual recovery.

Firmware Version	Upgrade Steps
3.0.x, 3.1.x, 3.2.x	» 3.4.0 » 3.5.0 » 3.6.30
3.3.x, 3.4.x	» 3.5.0 » 3.6.30
3.5.x, 3.6.x	» 3.6.30

Historical firmware version downloads can be found on Raritan.com/support.

#### **Raritan PX Downloads:**

The following supplemental files can be downloaded at Raritan.com/support (please select the correct product):

- Firmware Files and Release Notes
- Product Documentation and User Guides
- SNMP MIBs
- Related Tools and Drivers
- JSON-RPC SDK

#### **Release Package Details:**

The Xerus 3.6.30 release package has the below listed components. It is a limited availability (LA) release and only documentation will be posted on the Raritan website at Raritan.com/support. Please contact tech support if you believe that you need this update.

Xerus 3.6.30 Package components for PX3, PXO, BCM2, LP Switched, and LP Metered Products:

• "Xerus ReleaseNotes 3.6.30.pdf" (this file)

#### **General Upgrade Instructions:**

(standalone upgrade from the browser-based user interface)

• Enable JavaScript in your browser before logging into the unit to start the upgrade process.



- Follow instructions in the proper device User Guide. Please read the entire upgrade instructions before starting an upgrade.
- If you have any questions, or cannot follow the instructions in the User Guide, please STOP and contact Raritan Support for further instructions.

## **Contact Us**

For Raritan branded products, please go to Raritan.com/support for contact options.